PWI Inc. 109 S. KNIGHT WICHITA, KS 67213

Web: <u>www.pwi-e.com</u> E-mail: contact@pwi-e.com



Tel: 316-942-2811 Fax: 316-942-6209

FAA Repair Station # PJ2R085L EASA-145 # EASA. 145.5092

OPTIONAL SERVICE BULLETIN

Number: **03** Revision: **NEW**

Transmittal Sheet

Approved By: Signature on File	Date:	5/28/20	
Engineering Manager			
Approved By: Signature on File	Date:	5/28/20	
Ouglity Assurance			

Quality Assurance

The information and design disclosed herein was originated by and is the property of PWI, Inc. who reserves all patent, proprietary, design, manufacturing, reproduction, use and sale rights thereto, and to any article disclosed herein except to the extent rights are granted in writing to others by an authorized official of PWI, Inc. The foregoing does not apply to proprietary articles and/or designs of others.

This Service Bulletin is a fully approved and released engineering document of PWI, Inc.

PWI received FAA approval for the technical data in this publication that changes the type design.

Revision History:

Rev.	Description / Section Affected	Approval Signatures
		Primary Cognizant Engineer
		Engineering Manager
		Product Support Engineering
		Quality Assurance
		Certification Engineering
		Primary Cognizant Engineer
		Engineering Manager
		Product Support Engineering
		Quality Assurance
		~ ,
		Certification Engineering

Table of Contents

1.0	PLANNING:	4
1.1	Effectivity:	4
1.2	Concurrent Requirements:	4
1.3	Reason:	4
1.4	Description:	5
1.5	Compliance:	5
1.6	Approvals:	5
1.7	Manpower:	5
1.8	Weight / Balance:	5
1.9	References:	5
1.10	Publications Affected:	5
2.0	MATERIALS / PARTS REQUIREMENTS:	5
2.1	Material Requirements:	5
2.2	Availability:	5
2.3	Re-identified Parts:	5
2.4	Tools / Tooling:	5
3.0	ACCOMPLISHMENT INSTRUCTIONS:	6
3.1	Modification	6
3.2	Documentation of Modification	6

1.0 PLANNING:

1.1 Effectivity:

1.1.1 This Service Bulletin (SB) applies to PWI's STC# SA01748WI, part number 6910080-000.

A/C	Shipsets	Serial Numbers	Assembly P/Ns
Types	Simpsets		1100011019 17110
		B-28	
		LW-24	
		BB-410	
		LA-163	
		BB-938	
		BE-24	
		BE-115	
		BB-1004	
		LJ-1913 BB-595	
		BE-55	
		BE-30	
C90,		BB-1006	
C90A,		LJ-1246	
E90, F90,		LJ-843	
100, A100,	1-22	BB-697	
		BB-99	
B100,		LJ-740	6010000 000
200,		BB-1378	6910080-000
200C,		LW-271	
200T,		B-144	
B200,		B-154	
B200C,		LJ-773	
B200CT		BB-1356	
		BB-53	
		BC-67	
		BB-712	
		BB-1647	

1.2 Concurrent Requirements:

1.2.1 None.

1.3 Reason:

1.3.1 Some customers have noticed limited difference between dim and

bright mode.

1.4 <u>Description</u>:

1.4.1 This SB describes a procedure change the installation of the provided resistor.

1.5 Compliance:

1.5.1 Compliance with this SB is at discretion of customer.

1.6 Approvals:

- 1.6.1 This document has been approved by PWI engineering, and Quality departments and has received FAA approval for the technical data contained within the document that changes the type design.
- 1.6.2 Suitability of a particular assembly for modification is at discretion of modifying agency.
- 1.6.3 Quality assurance of modification described by this SB is responsibility of modifying agency.

1.7 Manpower:

1.7.1 Incorporation of this SB will require XX minutes per assembly.

1.8 Weight / Balance:

1.8.1 No weight change

1.9 References:

1.9.1 None

1.10 Publications Affected:

1.10.1 No publications are affected.

2.0 MATERIALS / PARTS REQUIREMENTS:

2.1 Material Requirements:

2.1.1 N/A

2.2 Availability:

N/A

2.3 Re-identified Parts:

None

P/N WAS:	P/N IS:
N/A	N/A

2.4 Tools / Tooling:

None


3.0 ACCOMPLISHMENT INSTRUCTIONS:


3.1 Modification

This service bulletin action will insure the resistor is set to its maximum resistance.

- 3.1.1 Turn off all breakers to power for main cabin.
- 3.1.2 Remove lamp cover plate by pulling gently on all sides.
- 3.1.3 Remove lamp 350-3380V003-001. You need not disconnect connector.
- 3.1.4 Add 1 each 1" x 3/8" piece of tape over the top of the already attached tape covering the location directly on top of the solder connections of the connector harness to the pc board.
- 3.1.5 Loosen screw on WW resistor and slide it as fare as it can go away from other lead wire and retighten screw.







New wire connections

- 3.1.6 Reattach lamp to cover plate.
- 3.1.7 Replace the cover plate back to its original location insuring all posts are securely in the rubber grommets.
- 3.1.8 After modification is made, switch breaker for cabin power back on.

3.2 Documentation of Modification

- 3.2.1 Identify accomplishment of this bulletin and modification on the inside of the lamp cover plate and/or the aircraft log book.\
- 3.2.2 This document supersedes service bulletin 02.